


MONUMENT RECORD

STATE OF INDIANA ~ COUNTY OF MONROE

Section 35, Township 10 North, Range 1 East,Monument Description & Remarks: 5/8" Rebar at Northeast corner of Section.COMPLETED BY *Steve Tanks*

I, Ben E. Bledsoe, Registered Land Surveyor, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 27th day of December, 2004 A.D.

Ben E Bledsoe

Indiana Registered Land Surveyor No. S0559



MONUMENT RECORD

Corner I.D. #

S-21


STATE OF INDIANA - COUNTY OF MONROE

Section Thirty-five, Township 10 North, Range 1 East

Monument Description & Remarks: Found 5/8" Rebar @ N-E Corner of section.

Used same witness trees as from a survey by Summerford, 1979. Survey
marker sign & post set.

Recovery Tie Drawing



● At Corner

N

Not To Scale

State of Indiana
County of Monroe

I, Michael W. Friley, County Surveyor, hereby certify
that this document was prepared under my direction in
accordance with the provisions of Section 17-3-64-4
through 17-3-64-8 of the Indiana Code, being Acts of 1965,
Chapter 319; and the above data is given under my hand and
seal this 25th day of April, 19 95 A.D.

Space
Reserved For
Recording
Officer

Indiana Registered Land Surveyor No. _____ or

Office of Monroe County Surveyor
United States Government Agency

Monroe County Surveyor
Title _____

Field Book:

95-01

Page:

32